# Metabo Quick Change System.

Change between drilling and screwdriving without tools in a matter of seconds ...

... and specialized applications like angled screws, screwdriving near the wall or working with extreme torque levels

QUICK

| Model | | Order no.* | 603184 BS 18 LTX-3 BL Q I | 603180 BS 18 LTX-3 BL Q I Metal | 603185 SB 18 LTX-3 BL Q I | 603182 SB 18 LTX-3 BL Q I Metal | 602359 BS 18 LTX BL Q I | 602361 SB 18 LTX BL Q I | 602362 GB 18 LTX BL Q I | 602334 BS 18 LT BL Q | 613156 BS 18 L BL Q | 613158 SB 18 L BL Q | 602320 BS 18 L Quick | 602217 BS 18 Quick | 601039 PowerMaxx BS 12 BL Q | 601749 PowerMaxx BS BL Quick | 600156 PowerMaxx BS Quick | 600385 PowerMaxx SB Quick |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Futuro Top quick-change chuck R+L, "QuickPlus" | | 627197000 | | ■ | | | | | | | | | | | | | | |
| Futuro Plus quick-change chuck S 1 M, "QuickPlus" | | 627189000 | | ■ | | | | | | | | | | | | | | |
| Futuro Plus quick-change chucks S 1 M/HM, "Quick" | | 627203000 | | | | | ■ | | ■ | ■ | | | | | | | | |
| Futuro Plus quick-change chucks S 1 M, "Quick" | | 627240000 | | | | | ■ | | ■ | ■ | | | | | | | | |
| Quick-change geared chucks "Quick" | | 627238000 | | | | | ■ | | ■ | ■ | | | | | | | | |
| Quick change threaded chuck Futuro Plus H 1 R+L, M4-M6 "Quick" H 1 R+L, M8-M12 "Quick" | | 627235000 627237000 | | | | | ■ | | ■ | ■ | | | | | | | | |
| Futuro Plus quick-change chuck H1 R+L, 1.5 - 13 mm, "Quick" | | 636608000 | | | | | | | | | ■ | ■ | ■ | ■ | ■ | ■ | ■ | ■ |
| Futuro Plus quick-change chuck H1 R+L, 1 - 10 mm, "Quick" | | 627259000 | | | | | | | | | ■ | ■ | ■ | ■ | ■ | ■ | ■ | ■ |
| Quick-change holder for bits and sockets "QuickPlus" | | 627341000 | | ■ | | | | | | | | | | | | | | |
| Quick-change bit holders "Quick" | | 627241000 | | | | | ■ | | ■ | ■ | ■ | ■ | ■ | ■ | ■ | ■ | ■ | ■ |
| Quick-change angle adapters "Quick" | | 627242000 | | ■ | | | ■ | | ■ | | | | | | | | | |
| Quick-change angle adapters "Quick" | | 627077000 | | | | | | | | ■ | | | | | | | | |
| Quick-change angle adapters "Quick" | | 627261000 | | | | | | | | | ■ | ■ | ■ | ■ | ■ | ■ | ■ | ■ |
| Off-set attachment BS LTX Quick | | 627343000 | | ■ | | | ■ | | ■ | | | | | | | | | |
| Off-Set Attachment "Quick" | | 627234000 | | | | | | | | | ■ | ■ | ■ | ■ | ■ | ■ | ■ | ■ |
| PowerX3 torque setting adapter | | 627256000 | | ■ | | | ■ | | ■ | | | | | | | | | |
| PowerX3 DC torque setting adapter | | 627232000 | | ■ | | | ■ | | ■ | | | | | | | | | |